



CORNER EVENTS ON A STRAIGHT ROAD

Idealease revolutionizes fleet operations with ELEVATE™, our proprietary Driver Performance System that improves driver safety and saves fleets millions of dollars in annual operating costs.

Sign up for the ELEVATE™ Question/Tip of the Week and receive short, actionable, and easy-to-use information to help your drivers operate their vehicles more safely while reducing fuel consumption, idle time, wear and tear on equipment, maintenance costs, vehicle downtime, and more.

If you have a question or a topic you would like covered in a future ELEVATE™ Question/Tip of the Week, email jerryring@idealease.com (<mailto:jerryring@idealease.com>).

Find a complete list of ELEVATE™ topics below.

Q: I was counseling my driver on corner events, and we found a couple events that appear to have happened on a straight road. Is the CyntrX device malfunctioning?

A: A malfunctioning device in this case is unlikely. The event trigger is an accelerometer in the device. As the event trigger, or accelerometer, is simply triggered by physical movement, it is safe to say that movement did occur.

More likely, this was a result of distracted driving where the driver made a correction maneuver that caused the associated side .3gForce required to trigger the event. These types of events are unlikely to be admitted by a driver in counseling unless there is other evidence, such as in-cab camera footage to help validate.

The goal is communication and improvement. Once you have the discussion, chances are the driver will become more aware and improve upon these habits.

24/7 ROADSIDE ASSISTANCE
CALL 1-800-435-3273

IDEALEASE, INC.
430 North Rand Road, North Barrington, IL 60010 | **847-304-6000** |