


*Q: How do I help my driver lower or eliminate the **corner events**?*

*A: When the accelerometer inside the CyntrX device detects a **.3gForce** movement to the side, it triggers a **corner event**.*

Most **corner events** we investigate are excessive speed on exit and entrance ramps or around sharp curves on roadways. Ramps and curves that are not gradual will have a recommended speed limit posted. Driving beyond that speed, particularly in a CMV, can cause the **corner event** trigger.

The number 1 way to reduce the corner events is to be aware of the safe speed signs and stay under that limit.



Idealease Business Intelligence is committed to helping your team Elevate their performance. You will get a weekly Question of the Week email that will help explain different elements of the scorecard, offer tips to improve Key Performance Indicators (KPI's) or other motivational topics to keep your drivers striving for excellence behind the wheel. If you have a question or would like a topic covered, please email jerryring@idealease.com.



Copyright © 2020, All rights reserved.

Our mailing address is:
430 North Rand Road
North Barrington, IL 60010

ELEVATE: QUESTION/TIP OF THE WEEK SIGNUP

Email *

First Name *

Last Name *

Job Title *

Company *

SUBMIT

[Register Here](#)